




CLAMPING METHODS



TYPE 1: Two M10 holes in triple clamp



TYPE 2: Four M8 holes in triple clamp

